



Fig. 1





Fig. 2


Fig. 3


Fig. 4

Fig. 5

VLR / MSC

SIM card
replaced

401

HLR

User information
updated

402

SCF

501

Service information, for user with IMSI 11222666

502

Error message




Fig. 6

HLR

SCF

SIM card
replaced

User information
updated

601

Note Subscriber Data Modified message
(Notification of new IMSI)

Register updated

NoteSubscriberDataModified

```

Not SubscriberDataModifiedArg ::= SEQUENCE {
    imsi,
    msisdn
    forwardingInfoFor-CSE
    callBarringInfoFor-CSE
    odb-Info
    camel-SubscriptionInfo
    allInformationSent
    extensionContainer
    ...
    replacementImsi
    subscription-Status
    subscription-Status
    extensionContainer
    ...
}

```

Fig. 8

